

sarom ™  
combinations unexpected



TEXTURE LOUNGE

MISS



MISS - 902



MISS - 909



MISS - 903




MISS - 906



MISS - 904



MISS - 905



MISS - 908



MISS - 901



MISS - 912



MISS - 910



MISS - 911



MISS - 907



MISS - 913





MISS - 917



MISS - 918




MISS - 916



MISS - 915



MISS - 914



MISS - 909

TEXTURE LOUNGE  
MISS

Design	Width (In Cms)	Weight	Composition	Tear Strength	Abrasion Resistance	Colour Fastness to Light	Pilling Resistance	Parten Repeat (If any)
MISS	142 - 145 CMS	380 - 400 GSM	96% Polyester, 4% Nylon	ISO 13934-2-1999; Instron CRE-1" Grab	More 40000 Cycles	4 or above	4-5 after 2000 cycles	N/A

1. We do not accept responsibility for any damage resulting from inappropriate use, chemical cleaning or additional impregnation.
2. Test results were gathered from various samples and therefore represent average indicative values.
3. Discolouration caused by clothing fabrics such as jenas does not represent a material defect. Minor colour deviations and discolouring in context of permissible industrial tolerance standards do not constitute reasons for claims .

Washing Instructions



Color may vary from batch to batch

Complimentary Sample File Not For Sale

Product Color May Slightly Vary From Original Due To Photographic Lighting Sources Or Your Screen Settings.



sarom ™  
combinations unexpected  
[www.sarom.co.in](http://www.sarom.co.in)